



PO BOX 189 | MILFORD, NY 13807 | 607-286-7244

www.otsegoruralhousing.org

PROJECT CLIENT

10 Factory St
Maryland NY 12116

Phone:

Note: All work must conform to NYS Building Codes. Contractor is responsible for obtaining Building Permits from the County or other jurisdiction. Permits must be on the job site prior to the start of work. Work items identified as Lead Based Paint Hazards must be corrected using HUD LBP Safe Work Practices. LBP Clearance testing will be done at the conclusion of work at all units with LBP hazards.

WORK PLAN

Please submit your price for the following item(s):

Return bids by: March 17, 2022

Plumbing Repairs: troubleshoot homeowner reports of virtually no water pressure in the kitchen and bath sinks; weak water pressure to toilet. Possible frozen lines – homeowner has had no real water pressure for 7 weeks. Pressure tank and hot water tank in basement appear to be functioning. Note pooling on front yard between old and new well heads. See photo.

Price (all labor & materials): _____

Comments:

Contractor Signature

Date